



FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

| UNIT TYPE: | | | | | | | | | | |
|-------------------|--|-----------------------|--|---------------|--|---------------------|----------|---------|--|--|
| Lined MSWLF | | LCID | | YW | | Transfer | X | Compost | | COUNTY: Lenoir PERMIT NO.: 54-08T FILE TYPE: COMPLIANCE |
| Closed MSWLF | | HHW | | White goods | | Incin | | T&P | | |
| CDLF | | Tire T&P / Collection | | Tire Monofill | | Industrial Landfill | | DEMO | | |

Date of Site Inspection: July 12, 2012 **Date of Last Inspection:** February 9, 2012

FACILITY NAME AND ADDRESS:

Onslow Container Service
 P.O. Box 9
 Deep Run, NC 28525
 NCSR 1511/ Bland Howell Rd.

GPS COORDINATES: N: 35.17373 W: 77.69637

FACILITY CONTACT NAME AND PHONE NUMBER:

Al Hill, Owner Phone 252 527 5040 Fax 252 523 0651
 Email: ahill@onslowcontainer.com

FACILITY CONTACT ADDRESS:

Same as above

PARTICIPANTS:

Wes Hare, NCDENR Solid Waste Section
 Al Hill, OCS Owner

STATUS OF PERMIT:

Issued July 7, 2011; Expires December 19, 2016

PURPOSE OF SITE VISIT:

Comprehensive Audit

STATUS OF PAST NOTED VIOLATIONS:

Not Applicable

OBSERVED VIOLATIONS

None

COMMENTS

1. The Certified Transfer Station Operators' documentation provided was as follows:

Russell Hill, Sr.: exp. 12/5/14
 Micah Schachinger: exp. 12/5/14

Scott Zesiger : exp. 11/13/12
 Cheryl Williams: current, date tbd
2. Current tonnages average 146 per day.
3. The service area for this facility is Craven, Duplin, Greene, Jones, Lenoir, Pitt and Wayne Counties.
4. The wind blown was minimal and is being managed well.
5. The signage at the front gate is as required.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

6. The tipping floor is washed with a hot water pressure washer.
7. Fire extinguishers are inside the transfer station and were reading a full charge.
8. The tipping floor replacement has been completed.
9. Lead acid batteries, white goods, and tires are not accepted at this facility.
10. The waste is being transferred to Republic in Bertie County.
11. Leachate is currently being collected in a 2,000 gallon tank and pumped as needed. The leachate is hauled to the City of Kinston's WWTP for proper disposal.
12. All access roads are paved with no erosion problems.
13. The facility is very well managed.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: 910.796.7405

Wes Hare
Environmental Senior Specialist
Regional Representative

| | | | | | | | | |
|------------------|-------------------------------------|-------|--------------------------|---------------|--------------------------|---------|--------------------------|---------------|
| Sent on: 7/13/12 | <input checked="" type="checkbox"/> | Email | <input type="checkbox"/> | Hand delivery | <input type="checkbox"/> | US Mail | <input type="checkbox"/> | Certified No. |
|------------------|-------------------------------------|-------|--------------------------|---------------|--------------------------|---------|--------------------------|---------------|

Copies: *Dennis Shackelford, Eastern District Supervisor
 *Jessica Montie, Compliance Officer